


73R3152

RedDOT
CORPORATION

FREIGHTLINER BRUSHLESS BLOWER MOTOR WITH HARNESS



Applications:

2003-17 Business Class,
2008-17 Cascadia & Cascadia Evolution
2012-16 108SD, 114SD & 122SD

Cross Reference

OEM Part No.: T77421A/2C

Replaces

VCC35000003, VCCT1000904A, T1000730D, VCC929709R, VCCT35000002

