

Of the thousands of SKUs that Red Dot has available to our dealer network, these parts are the hands-down best sellers to operators of Freightliner trucks. Stock up now and be ready for your next customer with Freightliner equipment. When it comes to design and manufacture of mobile HVAC, no one does it better. **Red Dot is Built to Survive!**


Compressor



75R81292Q

Sanden 4816, 4314S
QP7H15 - ABP N83 304314Q

Condenser



77R1279

Cascadia Dual Block
A22-67126-000, A22-66825-000, A22-66840-000,
A22-72250-000 - ABP N83 306033

Blower Motor



73R3002

Century, C Series, F Class
3949102, BOA80-415-00-429


Compressor



75R82312Q

QP7H15
Sanden 4417S, 4417S, 407S, 448S


Condenser



77R6978

Century, Columbia, FLD
1E5864, 1E6068, RDH RD4 6527 0

Receiver Drier



74R3328

Century, C Series, F Class
ABP N83 319614, 088335-00, 088535-00

Condenser



77R1277

Columbia, Coronado
A22-66824-000, A22-66839-000, A22-67125-000,
A22-72249-000 - RDH RD4 7131 0

Filter



78R5239

Century, C Series, F Class
A22-44665-000

Receiver Drier



74R3126

Century, C Series, F Class
ABP N83 319745, 088502-00, 088538-00

Receiver Drier




74R4028
Cascadia
A22-66700-00 - ABP N83 319015

Receiver Drier




74R4210
2008-2010 M2 Cascadia
Century/Columbia with Pad Type

Louver



72R2160
Various applications
ABP N83 317001

Expansion Valve



71R8301
FL Series
A22-18591-000, 329-406

Stato Seal kit



79R8950
All Models
ABP N83 322860

Expansion Valve



71R8453
Century, Columbia, C Series
ABP N83 308361, BOA80-321-00-269

Expansion Valve



71R8469
FL, C, Coronado
A22-45432-000 - ABP N83 308375

Distributed by

